



Figure 1—Does A&P mechanic training perpetuate misinformation and old wives' tales? You be the judge.

‘But My Mechanic Says...’

Aircraft owners get lots of bad advice from their A&Ps. Ever wonder where the A&Ps get it from?

“I KNOW YOU’RE A STRONG proponent of the in-flight mag check,” e-mailed the aircraft owner, “but I have been advised against doing this by my A&P due to concerns that I could get a serious backfire that could damage the engine. I read somewhere, maybe in one of your articles, that if the engine quits during the in-flight mag check, to pull the mixture first, then switch back to both mags before coming back with the mixture to prevent a backfire. Please advise...”

I told the owner that he had it exactly right, and his A&P had it wrong. For one thing, the A&P had his terminology mixed up: There’s zero risk of a “backfire” (which is combustion in the engine’s intake manifold). What the A&P was really concerned about is an “afterfire” (which is combustion in the exhaust manifold). Afterfires cause a scary “pop” noise but generally don’t hurt anything. Obviously, this aircraft owner had done his homework and knew perfectly well how to avoid this situation: If you turn off one magneto and the engine quits, pull the mixture control to idle-cutoff before turning the mag switch back to “both.”

For the A&P to advise against performing an in-flight mag check (which has compelling diagnostic value) because of concerns about an afterfire (which is extremely improbable, usually benign, and easily avoidable by the pilot) makes about as much sense as advising against flying the airplane altogether because of concerns it might crash if the pilot makes a mistake.

How about using a little common sense, and not throwing the baby out with the bathwater?

Last week, the director of maintenance of a large service center told one of my aircraft owner clients that one of his cylinders was unairworthy and would have to be removed, despite the fact that the cylinder’s compression measurement was fully 10 PSI above

Continental’s no-go threshold. When the owner asked why, the DOM explained that he could hear some air escaping through the cylinder’s exhaust valve, that the exhaust valve was part of the cylinder’s “static seal,” and that Continental states that “no leakage past the static seal is acceptable.”

If you read my last column in the July 2013 issue of *EAA Sport Aviation*, you know that Continental revoked this ridiculous guidance more than a decade ago. Continental’s current guidance (SB03-3) completely eliminates the distinction between the “static” and “dynamic” seal of a cylinder, and says it doesn’t really matter where the leakage is occurring, so long as it doesn’t exceed the no-go threshold (which is typically somewhere in the low 40s). But apparently this DOM missed that little detail and had been yanking jugs unnecessarily for the past 10 years at his customers’ expense. (I contacted Continental tech support in Mobile and had them send the DOM a friendly e-mail suggesting that he use the manufacturer’s current guidance and leave the cylinder alone.)

I’ve long noticed that whenever an aircraft owner brings his plane into the shop with a top-end problem of any sort (and

particularly an exhaust-valve problem), many mechanics reflexively blame the problem on “running too lean.” Burned valve? Obviously leaning too aggressively. Stuck valve? You must’ve been running too lean. High oil consumption? Low compression? No choke? Your fault, you leaned too much. (So far, I’ve yet to hear a mechanic blame fouled plugs on leaning too much, but I’m sure it’s happened.)

Apparently these mechanics have never been taught that modern piston aircraft engines need to be leaned aggressively to obtain optimum longevity, and that properly executed LOP operation is the kindest thing you can do for an engine. (The two TSIO-520s on my Cessna T310 are proof of that—both are at 205 percent of TBO.)

If you’re curious where mechanics come up with this stuff, let me suggest you need look no further than their A&P training.

WHAT A&PS ARE (AND AREN'T) TAUGHT

Although I’ve been an aircraft owner since the late 1960s and heavily involved in GA maintenance since the late 1980s, I didn’t actually become an official card-carrying A&P mechanic until the dawn of the 21st century, August of 2001 to be exact. So the process of training for the A&P knowledge and practical tests is still fairly fresh in my mind.

By the time I decided to go for my A&P ticket, I was already a pretty seasoned aircraft mechanic with a reputation for encyclopedic knowledge of aircraft systems and an aptitude for being able to troubleshoot thorny maintenance issues that had other mechanics stumped. I figured that passing the A&P exam would be a piece of cake.

I figured wrong.

By way of background, an applicant for an A&P certificate must surmount three

sequential FAA-imposed hurdles. First, the applicant must prove to his FSDO that he has the minimum required experience performing maintenance on civil aircraft: 30 months on a full-time basis, or 4,800 hours on a part-time basis. Second, the applicant must take and pass three multiple-choice, 100-question knowledge tests—mechanic general, mechanic airframe, and mechanic powerplant—and score at least 70 percent on each one. Third, the applicant must submit to an exhaustive (not to mention exhausting) oral and practical test with a designated mechanic examiner—the mechanic’s equivalent to a checkride—which is normally at least a full-day affair.

THE TESTS THAT TIME FORGOT

When I started studying for the three A&P knowledge tests, my first surprise was the study syllabus, which struck me as being firmly anchored in the 1940s.



S1 DIGITAL - The Quiet Revolution

Why settle for anything less than the best? For the aerobic pilots of Team Aerostars, anything but the best is simply not an option. That is why the team chooses to fly their formation routine with the S1 DIGITAL by Sennheiser.

Join Sennheiser in your pursuit of perfect sound.

www.sennheiser-aviation.com



SENNHEISER
The Pursuit of Perfect Sound

For example, in preparing for the powerplant test, I reviewed more than 1,000 multiple-choice questions from the FAA's "question bank" and found that the overwhelming emphasis was on radial engines, pressure carburetors, Hamilton Standard hydramatic propellers, and similar subjects of unquestionable interest to warbird buffs but of absolutely no relevance to contemporary GA aircraft of the sort that interested me.

There were only a handful of questions about horizontally opposed engines, perhaps two or three about fuel injection, only one about modern Hartzell compact hub propellers, and nothing at all about McCauleys.

The question bank for the powerplant test contained not a syllable about any technology that was less than 30 years old. Nothing about engine monitor data analysis, borescope inspections, spectrographic oil analysis, or scanning electron microscopy of oil filter contents. Nothing about compression ignition (diesel) engines, electronic ignition systems, FADECs, or lean-of-peak operation. Similarly, the airframe test was devoid of questions about composite construction (unless you count wood and fabric, which I suppose is the original composite).

To be fair to the FAA, there were actually lots of questions about "modern" 1960-vintage technologies, but they were all related to turbine and transport aircraft. To score a decent grade on the tests, it was obvious that I would need to master lots of material about turboprop and turbojet engines, air cycle machines, Roots blowers, and other esoterica that I knew I'd never remember or have any use for once the test was done.

MASTERING THE WRONG ANSWERS

This was frustrating enough, but what really bugged me was that the "official FAA answer" to many of these multiple-choice questions was often the wrong answer. It became obvious that if I wanted to get a good score on the mechanic knowledge tests, I'd have to commit these "FAA answers" to memory even though I knew that they were the wrong answers.

Would you like to see some examples? Here are some actual questions from the

2001 FAA mechanic exam question bank, with the "official FAA answer" that would be used by the FAA to grade the exam:

8072. Which fuel/air mixture will result in the highest engine temperature (all other factors remaining constant)?

A—A mixture leaner than a rich best-power mixture of .085.

B—A mixture richer than a full-rich mixture of .087.

C—A mixture leaner than a manual lean mixture of .060.

FAA-approved answer: C

Discussion: Stoichiometric mixture (peak EGT) is around 15:1 or .067, so the FAA-approved answer C ("leaner than .060" or about 17:1) would be very lean-of-peak, far leaner than most engines can run without unacceptable roughness (unless they are fuel-injected and have tuned fuel nozzles). This is definitely a mixture at which the engine would run cool, not hot.

Of the three choices given, the "most correct answer" is A. The FAA-approved answer (C) is just plain wrong, and perpetuates the old wives' tale that rich mixtures are cool and lean mixtures are hot. With training like this, is it any wonder so many A&Ps blame almost every cylinder malady on LOP operation?

8678. Why must a float-type carburetor supply a rich mixture during idle?

A—Engine operation at idle results in higher than normal volumetric efficiency.

B—Because at idling speeds the engine may not have enough airflow around the cylinder to provide proper cooling.

C—Because of reduced mechanical efficiency during idle.

FAA-approved answer: B

Discussion: None of the given answers is correct, but the FAA-approved one is the probably the worst possible choice, because it suggests that pilots should keep the mixture full-rich during idle and taxi in order to obtain proper cooling. Do you suppose that the OWT explains

why so many pilots taxi around at full-rich and foul the crap out of their spark plugs? Are they learning this from their A&Ps?

Here's the correct answer: "Because a very rich mixture is required for cold-starting, and aircraft carburetors don't have a choke to provide such a rich mixture (the way automotive carbs do), the idle mixture has to be set extremely rich...which is why as soon as the engine starts to warm up, you need to come back on the mixture control." Of course, that answer isn't one of the choices offered.

8773. Carburetor icing is most severe at...

A—air temperatures between 30°F and 40°F.

B—high altitudes.


C—low engine temperatures.

FAA-approved answer: A

Discussion: Are you kidding me? At OAT between 30°F and 40°F, air seldom contains enough moisture to create severe carb icing. Once again, the correct answer isn't offered: "Cessna 182 on a humid day in Florida."

The AOPA Air Safety Foundation briefing on carb ice states, "Icing is most likely to occur—and to be severe—when temperatures fall roughly between 50°F and 70°F and the relative humidity is

Figure 2—An applicant for an A&P certificate must take and pass three multiple-choice, 100-question knowledge tests.



greater than 60%.” It shows a gory photo of the fatal crash of a Cessna 182 caused by carb ice that formed at OAT 80°F and dew point 45°F.

If the FAA genius who wrote this question was a pilot, it’s a sure bet that most of his experience is flying Gulfstreams, not Skylanes. (Keep in mind that to get a decent grade on the A&P knowledge test, you have to memorize these FAA-approved wrong answers, or risk failing!)

8829. Which of the following defects would likely cause a hot spot on a reciprocating engine cylinder?

A—Too much cooling fin area broken off.

B—A cracked cylinder baffle.

C—Cowling air seal leakage.

FAA-approved answer: A

Discussion: Once again, the FAA offers three possible answers and then claims that the “wrongest” is the one it considers

When I started studying for the three A&P knowledge tests, my first surprise was the study syllabus, which struck me as being firmly anchored in the 1940s.

correct. Every IA I’ve asked agrees with me that by far the most likely cause is a bad baffle (answer B), and none has ever seen a case where a cooling fin was broken off badly enough to create an issue.

8982. If a flanged propeller shaft has dowel pins...

A—install the propeller so that the blades are positioned for hand propping.

B—the propeller can be installed in only one position.

C—check carefully for front cone bottoming against the pins.

FAA-approved answer: B

Discussion: Well, that’s interesting. The Continental TS10-520-BB engines on

my 1979 Cessna T310R have flanged propeller shafts. Each flange has a pair of identical dowel pins spaced 180 degrees apart. This permits my three-bladed McCauley C87 props to be installed in two possible orientations, one that results in the vertical blade pointing down when the engine stops, and the other that results in the vertical blade pointing up. According to the Cessna service manual, only one of these orientations is the correct one, so you need to be careful when installing the prop. The FAA-approved answer (B) is just plain wrong. So are the other two answers.

I could go on, but you get the idea.



CTLSi Jubilee Series



25th Anniversary of Flight Design
Limited Jubilee edition - 25 planes available only!

Flight Design USA email: flightdesignusa@rcn.com
Tel: 860.963.7272 web: www.flightdesignusa.com

Jubilee Series Features:

- 100-hp Rotax 912iS
- 2,000 hours TBO
- Auto fuel or avgas
- MTOW – 1320 lb
- Max. range – 974 NM
- Cruise speed – 120 kts
- Special Jubilee exterior design
- Special two-tone leather interior
- BRS parachute system
- Electric stabilator trim
- Mode S Transponder
- GPS Garmin 796 XM
- KANNAD ELT 406 MHz
- GTN 750 (optional)
- NAV radio (optional)
- SV-ADSB function (optional)
- Two Bose A20 ANR headsets
- PM 3000 intercom, ELT 406 MHz
- Dynon Dual Screens SkyView SV – D1000
- Dynon Autopilot – commanded by SkyView






Figure 3—Here's irrefutable proof that I was able to remember all those FAA-approved wrong answers long enough to score 96, 99, and 99 on my three mechanic knowledge tests.

A CHARACTER-BUILDING EXPERIENCE

Well, it took me many hours of study, practice, and drill to memorize all of the FAA-approved wrong answers to the thousands of multiple-choice questions in the question bank. As you can imagine, going through this mind-numbing exercise was a character-building experience that greatly expanded my vocabulary (of expletives) and bolstered my respect for the cutting-edge mindset of our favorite friendly federal agency.

I guess I must've done a workmanlike job of studying and memorizing, because when I finally took the three FAA knowledge tests at my local LaserGrade computerized testing center, I scored 96 percent on the general and 99 percent on both the airframe and powerplant. (See Figure 1.) I don't want to brag, but it's a rare skill to master so many wrong answers so consistently in such a short period of time, if I do say so myself.

Once the exams were done and my scores were in the bag, I celebrated with the obligatory overnight soak of my brain's medial temporal lobe (seat of long-term memory) in a 50-50 mixture of cheap champagne and methyl ethyl ketone, just to make absolutely sure all those FAA-approved wrong answers and old wives' tales were permanently purged from my gray matter. After all, it would certainly be embarrassing to inadvertently pass any of them on to the next generation of A&P mechanics, wouldn't it? *EAA*

Mike Busch, EAA 740170, was the 2008 National Aviation Maintenance Technician of the Year, and has been a pilot for 44 years, logging more than 7,000 hours. He's a CFI and A&P/IIA. E-mail him at mike.busch@savvyaviator.com. Mike also hosts free monthly online presentations as part of EAA's webinar series on the first Wednesday of each month. For a schedule visit www.EAA.org/webinars.

Listen up and fly right

Rich Sugden, ATS customer

KRT2 Comm Radio
Complete Control from AF-5000 EFIS
6W transmitter, integrated VOX/Intercom,
Dual frequency monitoring
Starting at \$1,250

DITTEL
AVIONICS
ATS

visit us online @ atsinc.aero

Better Aircraft Fabric™
General Aviation Products
Aircraft Fabric and Decal systems for your Airplane, no paint necessary!

You love fabric covered airplanes, but . . .

- Do you want to save over half the time it takes to fabric-cover your plane?
- Are you sick and tired of painting, sanding and solvents?
- Do you want to save half the cost of getting airworthy results?
- Are you annoyed by paint cracking off the base fabric?
- Are you looking for significant weight-saving and super easy repairs and mods?

if that is the case, please have a look at: www.betteraircraftfabric.com

ORATEX6000™ AND ORATEX600™
Quality made in Germany by Lanitz Aviation

Tel: (907) 229-6792
web: betteraircraftfabric.com
email: Lars@betteraircraftfabric.com

The "Alaska-proof" Aircraft Fabric

2013 ADVENTURE AWARDS
1157